




Low 2512



June 24, 1957

ED:

On June 21, 1957 we shipped one "H" type window (111-0967) to  25X1
 This window completes the third set of "C" Configuration windows. 25X1

When you receive it you will note that there is a large hollow on the step of one side, plus a minor one on another edge.


During manufacture some flaw at the edge started a cleavage plane at this hollow. We noticed it in time to stone (i.e. grind and polish) it out, leaving the hollow. I know that you are dependent upon this surface for sealing. In the interests of delivery and your need for it we continued with the piece rather than scrap it. Can you seal at this point with a thiokol compound?

[Signature]

TWM:hmm ✓
cc: GK



25X1



25X1

~~SECRET~~


DMK

SAFC 17 / 33
CCPV 20F 2

24 JUN 1957

ATTN : Project Director/AQUATONE
Administration Officer/Finance
Deputy Director of Security (Investigations and Support)

PROJECT AQUATONE (OCTROI)
#113458



25X1

FOR THE DIRECTOR OF SECURITY:

25X1



25X1

~~SECRET~~